

- ① Uliga Dock A (3.4.2.1)
- ② Uliga Dock B (3.4.2.2)
- ③ Uliga Dock Warehouse (3.4.3.1)
- ④ U.S.A.I.D. Disaster Mitigation Relief Building (3.4.3.2)
- ⑤ Guard House (3.4.3.3)
- ⑥ Pump Vault (3.4.3.4)
- ⑦ Marshall Islands Shipping Corporation
- ⑧ MIMRA Outer Island Fish Market Center
- ⑨ Ministry of Transportation Office
- ⑩ Abandoned MSTCO Building
- ⑪ Uliga Inner Basin/Small Vessel



Depths are approximate and were taken from dock with an anchor, line, and markings on rope at 1-meter intervals. Depth readings were taken at a higher tide that was +/- 1 meter higher than low tide, so readings were reduced by 1 meter in order to get readings for a typical low tide depth.

